

Appendix F: Condition and Use of Wilderness Access/Cherrystem Routes

| <u>Wilderness Area</u> | <u>Cherrystem/ Boundary</u> | <u>Total Length (in miles)</u> | <u>Type of Access</u> | <u>Condition</u> | <u>Date</u> |
|-------------------------|-----------------------------|--------------------------------|---|---|----------------|
| North Jackson | Deer Creek Ranch | 2.85 | Four-wheel drive vehicle (2 miles) | First segment passable by four-wheel drive vehicle for two miles. Remaining portion is washed out largely indiscernible, impassable to any vehicle and does not appear to have been used for ten (10) years or more. | December 2000 |
| | North Fork Jackson Creek | 0.56 | Foot/ Horseback | Impassable to vehicles. No evidence of vehicle use for at least 10-15 years prior. Large sagebrush, cottonwood and mahogany growing from the road bed. | October 2003 |
| | New Years Canyon | 1.33 | High-clearance vehicle | Passable to high-clearance vehicle. No evidence of vehicle use several years prior. | September 2001 |
| | Deer Creek Peak | 1.14 | Four-wheel drive vehicle | Route is rough and heavily eroded. Actual route differs from mapped location for segment furthest from main road. | December 2000 |
| | Happy Camp | 0.74 | Four-wheel drive vehicle | Located beyond private lands posted no trespassing. Public access not currently available. | December 2000 |
| | Parrot Peak | 0.55 | High-clearance vehicle | Outwash sediments of small to medium cobble. | December 2000 |
| South Jackson Mountains | Christiorsonn Canyon | 0.72 | High-clearance vehicle | Located in outwash plain of Jackson Creek. Evidence of past channelization is evident and likely to occur in the future | December 2000 |
| | Bliss Canyon | 0.82 | High-clearance vehicle | Lower segment entrenched through alkaline soils and lake deposits, upper segment covered with large rocks and small boulders. | December 2000 |
| | Mcgill Canyon | 0.6 | High-clearance vehicle | Located on alluvial fan of McGill Creek. Route eroded, crossed with braided channelization, large rock and cobble. | December 2000 |
| | Buckbrush Springs | 1.27 | High-clearance vehicle | Located on alluvial fan. Route eroded and braided. No visible evidence of previous vehicle use along furthest segment. | December 2000 |
| | Bull Creek | 2.55 | High-clearance vehicle | Lower segment entrenched through alkaline soils and lake deposits and crossed by several small seasonal drainages. Upper segment covered with large rocks and small boulders. Upper and lower segment separated by private property with no easement or right-of-way. | December 2000 |
| | Clover Creek | 1.91 | High-clearance vehicle | Route deeply entrenched and eroded in clay soils. | December 2000 |
| | Talimidas Springs | 0.72 | High-clearance four-wheel drive vehicle | Route deeply entrenched and eroded in clay soils. | December 2000 |
| Pahute Peak | North Fork Clapper Creek | 1.07 | High-clearance vehicle | Located on lake sediments and rhyolite soils. Crossed by small seasonal drainages with large cobble. | December 2000 |

Appendix F: Condition and Use of Wilderness Access/Cherry Stem Routes

| | | | | | |
|----------------------------|-------------------------------|------|---|--|----------------|
| | Clapper Creek | 2.37 | High-clearance vehicle | Located on lake sediments and rhyolite soils. Crossed by small to moderate seasonal drainages with large cobble and boulders. | December 2000 |
| | Black Notch | 1.76 | High-clearance vehicle | Located on lake sediments and rhyolite soils. Crossed by small to moderate seasonal drainages with large cobble and boulders. | December 2000 |
| | Fluorite Mine | 1.38 | High-clearance vehicle | Located on lake sediments and rhyolite soils. Crossed by small to moderate seasonal drainages with large cobble and boulders. | December 2000 |
| | Indian Creek | 2.13 | High-clearance vehicle | Lake sediments of sand and gravel along lower segment, becoming rough with angular rocks and small boulders. | December 2000 |
| | White Rock Springs | 2.31 | Full-size vehicle | Route crossed with small seasonal drainages. Lake sediments of sand and gravel. | December 2000 |
| High Rock Lake | Donnelly Creek | 1.08 | High-clearance four-wheel drive vehicle | Located within and along drainage consisting of sand to large cobble. Crosses riparian area and is causing noticeable damage to that resource. Area at end of routes is not large enough for full-size vehicles to turn around—resulting in further resource damage. | December 2000 |
| | Lower Cherry Creek | 1.02 | High-clearance vehicle | Route located on basalt with small to moderate size boulders. | December 2000 |
| | Sheep Butte | 2.91 | High-clearance vehicle | Route covered with broken rock and small boulders. Centerline consists of low sage and forbs | December 2000 |
| Calico Mountains | Morman Dan South | 0.96 | High-clearance vehicle | Route located on alluvial fan. Lake sediment, gravel, and sand at lower levels of road. Large rocks in upper segment. | December 2000 |
| | Morman Dan North | 1.66 | High-clearance vehicle four wheel drive | Segments of route very narrow. Large angular rocks in upper end of route. | December 2000 |
| | Burro Spring | 0.74 | High-clearance four-wheel drive | Route initially crossing lake sediments. Upper segment crossed by small to large seasonal drainages with large angular rock, cobble, and boulders. | December 2000 |
| | Black Canyon | 0.71 | Full-size vehicle | Route located on ridge-top of broken and weathered small angular rock. | December 2000 |
| East Fork High Rock Canyon | Cottonwood Creek (Shoestring) | 3.85 | High-clearance vehicle | Beginning of route crossed by moderate seasonal drainage with sand and small cobble. Remaining portion located on rhyolite and lake sediments consisting of decomposing rock, sand and silt. | December 2000 |
| | Bernard's Corral | 2.5 | High-clearance vehicle | Beginning of route crosses moderate perennial drainage followed by segment of decomposing rhyolite covered with small to medium size angular rock. Remaining portion located on rhyolite and lake sediments consisting of decomposing rock, sand and silt. | December 2000 |
| High Rock Canyon | South Yellow Rock | 2.41 | High-clearance vehicle | Road surface covered with angular basalt rock with occasional small to moderate size boulders. | September 2001 |
| | North Yellow Rock | 2.77 | High-clearance vehicle | Road surface covered with angular basalt rock with occasional small to moderate size boulders. | September 2001 |
| Little High | McConnell | 0.86 | High-clearance | Located on lake sediments and rhyolite soils. | December |

Appendix F: Condition and Use of Wilderness Access/Cherrystem Routes

| | | | | | |
|-------------|----------------|------|--------------------------|--|---------------|
| Rock Canyon | Canyon | | four-wheel drive vehicle | Crossed by small to moderate seasonal drainages with large cobble and boulders. | 2000 |
| | Butte Springs | 2.56 | High-clearance vehicle | Route located on basalt with large angular rocks and boulders. Route crosses moderate sized seasonal drainage. | December 2000 |
| | Laxaque Spring | 2.12 | High-clearance vehicle | Route located on basalt with large angular rocks and boulders. | December 2000 |